



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date: September 29, 2006

Supervisor 1021

Mine Name: Hurricane Sandstone
Operator Name: Feller Enterprises
Allen Feller
708 East 1100 South
St George, Utah 84790

Permit number: S/053/077
Date: September 14, 2006
Time: 7:30 AM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Active

Weather: Warm

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated Comment Enforcement

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Checked the site while in the area.

Directions to Site:

See previous inspection report.

Inspection Summary:

The operator has not disturbed much additional acreage since My last visit to the area on September 29, 2005. I walked the area to GPS the disturbance but the GPS file was corrupted and the map of the area could not be printed. I will attempt to GPS the area during my next visit.

Conclusions and Recommendations:

I will revisit the site at a later time to GPS the total disturbance at the site.

Inspector's Signature

Doug Jensen

Date:

9/29/06

dj:pb

cc:

Feller Enterprises

Russ Schreiner, BLM, St George FO UTU-080545

O:\M053-Washington\S0530077-HurricaneSandstone\inspections\091402006insp.doc